

## **TECHNICAL BULLETIN No. 003-2014**

07-02-2014

Model: MP3 500 - Fuoco 500

Subject: New calibrations

Dear Dealer,

The new calibrations for the aforementioned models are now available via the PADS diagnostic tool;

MP3 500 – Fuoco 500 Calibration: 1233GP41

The new software introduces the following functional improvements:

- improved idle management;
- increasing the engine idle speed by about 150 rpm;

After installing the new calibration, perform the following operations:

- run engine at idle speed for 10 minutes to auto-adapt fuel/air mixture;
- turn ignition key off and on 5 times;
- wait approx. 15 seconds for power latch to complete before starting again.

Best Regards,

Piaggio & C. SpA Spare Parts, Accessories and Aftersales Technical Service BU